140H Differential and Bevel Gear Repair Options



PLANNED/PROBLEM INDICATORS

- Component hours
- Differential oil leak
- S•O•S[™] report

BUILT FOR IT

- Noise or vibration
- Failure of another component within same oil system
- Machine down for other work

PART OR SERVICE INCLUDED

- All bushings and anti-friction bearings
- All seals and gaskets
- All thrust washers/spacers
- Miscellaneous hardware (as needed)



- >> Provides new component life (if other parts meet reusability guidelines)
- >> Guaranteed price
- >> Reduces costs
- >> Reduces downtime

INSPECTION POINTS

- Gears
- Bevel pinion shaft
- Limited slip clutch discs and plates
- Limited slip clutch piston and housing
- Differential spider
- Differential case assembly
- Operation test

\$ 1,202.27

LEVEL 2 ADD-ONS Salvage or Replace	Estimated Price
Bevel gear	\$
Bevel pinion shaft	\$
Differential spider gears	\$
Differential side gears	\$
Differential spider	\$
Limited slip clutch discs	\$
Limited slip clutch plates	\$
Limited slip clutch piston	\$
Limited slip clutch housing	\$
Differential case assembly	\$

Warranty	
Contact Phone No.	
Date	
Model	
Serial No.	
Total Estimated Price	
Sales Person	
Contact Phone No.	
Turn Around Time	
	(SMCS code 024 for Level 1, 028 for Level 2)

(SMCS code 02A for Level 1, 02B for Level 2)



www.cat.com

 $\ensuremath{\textcircled{C}}$ 2016 Caterpillar • All Rights Reserved • Printed in USA

CAT, CATERPILLAR, BUILT FOR IT, their respective logos, "Caterpillar Yellow," the "Power Edge" trade dress as well as corporate and product identity used herein, are trademarks of Caterpillar and may not be used without permission.



Level 1 - blue Level 2 - yellow

© 2016 Caterpillar • All Rights Reserved • Printed in USA CAT, CATERPILLAR, BUILT FOR IT, their respective logos, "Caterpillar Yellow," the "Power Edge"trade dress as well as corporate and product identity used herein, are trademarks of Caterpillar and may not be used without permission.

